

HIWRAP

Submitted by **gheymfield** on Sun, 08/22/2010 - 00:10

- **HIWRAP**

Flight Date:

Thursday, August 19, 2010

HIWRAP worked fine during first flight but then developed an intermittent problem in the digital receiver while making changes after the flight. This means that the data quality will be bad at times. We're still trying to track down the problem as to whether it is a loose connection or a board problem. Access to the plane has slowed diagnosis of the problem. We will work on the problem tomorrow but more likely Monday after the CST when the crew can remove the radome so the digital receiver can be accessed. Otherwise the system functions well.

Status:

Yellow